
## CORRES. CONTROL INCOMING LTR NO.



DATE

**ACTION** 

DIST.	£7	A FM
BENJAMIN. A.	┰╴	Т
BERMAN, H.S.	┰	┿
BERMAIN, N.S.	+-	+
BRANCH, D.B. BURLINGAME, A.H.		
BURLINGAME, A.H.	4-	-
CARNIVAL, G.J.		
COPP, R.D.		
CROUCHER, D.W.	$\Gamma$	$T^{-}$
DAVIS J.G.	$\top$	7
EVERED, J.E.	Z	7
FERRERA, D.W.	*	╅—
GOODWIN, R.	┿	+-
GOODVIIV, N.	╃┈	+
HANNI, B.J.	+-	╀
HEALY, T.J.	↓_	1.
HILBIG, J.G.		1_
IDEKER, E.H.		Į
KERSH, J.M.	$\nabla$	7
KIRBY, W.A.	1	1-
KRIEG, D.	+-	+
KUESTER, A.W.	┿	┰
LEE EAA	+-	+
LEE, E.M. MAJESTIC, J.R.	4	↓_
MAJESTIC, J.R.	╀	₩
MARX, G.E.	1_	丄
MORGAN, R.V.	1	1_
PIZZUTO, V.M.		Т
POTTER, G.L.	X	1
SANDLIN, N.B.	1	$\top$
SHEPLER, R. L.	1	<del>  -                                    </del>
SHOWAN, M.T.	-	+-
SON, E.R.	╌	┼
SON, E.H.	╀	₩
MAN, K.G.	┞	↓
E. J.S.		<u>L</u>
INSON, R.B.	_	_
WILSON, J.M.		
YOUNG, E.R.	П	$\sqcap$
ZANE, J.O.	_	_
	┼─	<del>  -</del>
Schubert A	1	<del> </del>
20 Mary 17	Ю.	⊢
F/ 1/2	h -	—
Edneck P	$\boldsymbol{\varkappa}$	—
-	_	_
Light GS	$\searrow$	
House, CH	X	$\overline{}$
77		
Bunn D	abla	
Bunge P	~	

CORRES CONTRO

Reviewed for Addressee Corres. Control RFP 4-92

BY

## Department of Energy

ROCKY FLATS OFFICE GOLDEN, COLOHANO 182402-092815 111 '92

> ROCKY FLATS FLANT CORRESPONDENCE CONTROL MAR U 6 1992

92-DOE-2599

Mr. Scott Winters Colorado Department of Health **UST** Coordinator Hazardous Materials and Waste Management Division 4210 East 11th Avenue Denver, Colorado 80220

Dear Mr. Winters:

The U. S. Department of Energy is preparing to permanently close a petroleum underground storage tank (UST) at the Rocky Flats Plant in Golden, Colorado. The UST will be removed and the site closed in accordance with the provisions of the State Inspector of Oils Underground Storage Tank regulations, 7 CCR 1101-14 Part 8.71, and the Colorado Department of Health Underground Storage Tank regulations, 6 CCR 1007-5 Part 280.71.

The enclosed Rocky Flats Plant Map shows the location of the UST, which is to the north of Building 776. The UST previously provided diesel fuel to an inactive Fluidized Bed Unit. Records show that the tank was installed in 1968 and is of a single wall steel construction with a capacity of approximately 1,000 gallons. The suction fuel delivery system is also of a steel single wall construction. The UST was emptied and temporarily closed in March 1991 pending retrofit upgrades to install automatic release detection equipment and spill and overfill equipment. Subsequently, it has been determined that the UST no longer is required to support facility operations and may be permanently closed.

Work plans are currently being developed to initiate field closure activities by late March of this year. Upon completion of the project, a completed Notification for Underground Storage Tanks form will be submitted to your office. Notification of a suspected release will also be provided to your office in the event that evidence of petroleum contamination is present in the soils and/or ground water at the site.

If you have any further questions regarding this matter, please contact Tom Lukow at 966-4561 or Stacey Eriksen at 966-5920.

Sincerely,

Assistant Manager

for Environmental Management

Enclosure

cc w/Enclosure:

T. E. Lukow, WMED, RFO

## Mr. Scott Winters

cc w/o Enclosure:
F. Lockhart, ERD, RFO
A. L. Schubert, EG&G
P. W. Edrich, EG&G
G.S. Taylor, EG&G
C. H. Hayes, EG&G
R. Leu, U. S. EPA Region VIII